Buildi	ngs Pro	ojects	& Mai	intenance	2023			
NOW	Routine	Project						
	04:00							
IOWN	Office		-					
	Priority	Status	Date Added	Item	Est Cost	Notes	Last Done	Next
				Older equipment and seasonal storage in Royal Arch Room	\$100	Find permanent storage or dispose of		
				Heat Pump Maintenance	\$400	Annual Clean of Units in Protectworth Rm, Town Office, Selectmen's Office	July 2023	2024
				Propane Furnaces Maintenance		Routine Maintenance		
				Generator (Propane) for Town Offices		Routine Maintenance		
				Roof Inspection				
				Perimeter drains: Check, Flush, make sure all PVC pipe is covered (protected from sunlight)				
				Inspect / Repair siding, flashing				
				Windows/Doors and Window		Likely heat loss in winter due to		
				Shades need to be inspected,		poorly functioning windows.		
				adjusted and repaired as necessary		Southern exposure yields intense		
				to ensure operability		heat on sunny summer days Install / Repair interior shades (Awnings considered but expensive and need frequent		
						repairs/replacement)		
				ADA ramp needs regular sanding/sealing, nails need ocasional resetting				
				Main entrance door at Town Office	\$3500	Door has been sprung multiple		
				needs attention (Casing? Door? Hardware?)		times, casing is not fitting leading to heat loss.		
Librar	v							
	<b>y</b> Priority	Status	Date Added	Item	Est Cost	Notes	Last Done	Nex
				adjustable book shelves starting to		Some shelves are becoming 'tippy'		
				show age				
				Exterior Hours sign is showing age		New sign similar to Town Office?		
			<u></u>	Popcorn machine and various items stored by passthru door to Royal		Safety concern? Indicates additional storage required?		
				Arch Rm (basement level) Routine Lift Maintenance (recertify				
				Noutine Lift Maintenance (recertify				

			Windows/Doors and WindowShades need to be inspected,adjusted and repaired as necessaryto ensure operabilityMain entrance door at Library needsattention (casing? Door? Hardware?	\$3,500	Should probably be done at same time as Town Office Entryway Door		
Dolico Dono	rtmont						
Police Depa Priority	Status	L Date Added	Item	Est Cost	Notes	Last Done	Next
		Auueu	Police Dept Windows are drafty. boarded up but lacking insulation	\$2,500	Tremendous heat loss. Similar exposure windows in Royal Arch Room also drafty. Add internal draft reduction? Magnetic interior storm windows?Police Dept Baseboard heat can't keep up on cold winter days. Add Baseboard?		
			Police station is not visible.		Add Signage? Side of Building?		
			No handicapped access of any kind				
			Computer (Server) is in the old oil tank room				
			Evidence / Armory Room is		Armory room would ideally be		
			supposed to be secured		separate - and secured.		
lighway / F		امانيم					
iigiiway / F	ire Bui	laing					
Priority	Status	Date	Item	Est Cost	Notes	Last Done	Next
			Item Fiber was never moved to underground conduit due to weather	Est Cost	Notes Needs to be moved underground while conduit is thawed. Was to have been done at install. Consolidated? Fidium?	Last Done	Next
		Date	Fiber was never moved to underground conduit due to weather Highway phone system is	Est Cost	Needs to be moved underground while conduit is thawed. Was to have been done at install.	Last Done	Next
		Date	Fiber was never moved to underground conduit due to weather	Est Cost	Needs to be moved underground while conduit is thawed. Was to have been done at install. Consolidated? Fidium?	Last Done	Next
		Date	Fiber was never moved to underground conduit due to weather Image: Conduct of the second	Est Cost	Needs to be moved underground while conduit is thawed. Was to have been done at install. Consolidated? Fidium? Modify setup? Training? was not inspected, but has had no sealant treatments in recent	Last Done	Next

			Modine Oil Heater Maintenance		Routine Maintenance		
			Renai Propane Heater Maintenance		Routine Maintenance		
			Generator (Propane) for Emergency		Routine Maintenance		
			Services Bldg				
			Metal Siding mostly intact, several	5,000.00	Constant damage from Snow and		
			areas could use repair/replacement		Ice dropping off roof and plowing.		
					Solid HD 3 foot wall for protection?		
			Evidence of wet roof insulation =		Heavy condensation during heating		
			tremendous heat loss		season. Strong possibility of		
					developing mold - health hazard.		
			Highway garage doors are too		Major project. Straightforward due		
			narrow for town trucks - leading to		to the fact it is a steel building.		
			damage of the doors, building and		Adding a steel header beam over		
			trucks		the existing doors, new doors could		
					be installed at virtually any widths.		
			Roof likely needs significant work		was not inspected, but has had no		
					sealant treatments in recent		
					memory.		
			New LED lighting on fire side	\$2,500	was installed by highway crew on		
			(already upgraded on hiway side)		highway side for \$1000 - work area		
					was very dark with the old		
					florescents - Need on FIRE side		
			Fire side has no catwalk beneath		Highway side has catwalk built by		
			heaters for maintenance.		hiway crew for extra storage and		
					access to heaters.		
			Oil fired heaters are problematic,		Oil heaters vent thru roof, hurting		
			fed by unreliable pump		roof integrity. Oil has spilled at least		
					twice due to faulty sensor in		
					pumping line. Ongoing discussions		
					about transitioning to propane		
Meeting H	louse						
		Date					
Prior	ty Status	Added	Item	Est Cost	Notes	Last Done	Next
			Door Closing Hardware on 'Ramp				
			Door" has come loose				
			1st Floor Door to Lift is not		Tamara has contacted installer		
			functioning				
			Rear Lantern Lights on both doors		water and insect entry point.		
			(1st and second floor) are wobbly		Abandoned hornet nest on 2nd		
					floor fixture.		
			Non functioning electrical outlet		Is this on a timer for the Christmas		
			near main outdoor breaker box.		Lights?		
			NOTE: Evidence of mouse and bats		They're BACK!		
		1	in attic.			1	

Front of building has persistent film		Cause should be investigated as		
of insects? Pollen?		cleaning has been shown to be a		
		temporary fix		
Prune plantings around building		Touching building, holding moisture		
have grown too close to building		and wearing paint.		
		Replace with smaller version?		
Remove large evergreen.		Replace with smaller version?		
Rot visible on both front exterior corners				
Plaster ceiling at top of staircase to sanctuary is peeling		no evidence of moisture in attic above		
Right entry stairway has settled away from building		Check flashing. Minimize gap (safety issue - could catch crutch or cane) could be evidence of a drainage issue.		
Windows Sills Need Attention. Cleaning, Filling Gaps, Sanding and				
sealing				
Electric Wire hanging over building sign.		remove back to nearest junction. Patch and repair hole.		
Possible water damage in sanctuary		SW back corner, above fire exit,		
ceiling		and at chimney area. (could be damage prior to new roof)		
Remove non functioning thermostat		to avoid leaving heat on		
<del>in front of sanctuary</del>		unecessarily! Mason completed Aug 2023	Aug '23	
Women's Bathroom Door needs				
adjustment				
Closet adjacent to stairs should be				
cleaned out.				
cleaned out. CLOSET: Phone and internet wiring				
CLOSET: Phone and internet wiring	200.00	Time to retire and remove		
CLOSET: Phone and internet wiring should be secured	200.00	Time to retire and remove		
CLOSET: Phone and internet wiring should be secured Piano	200.00	Time to retire and remove		
CLOSET: Phone and internet wiring should be secured Piano Insulation in basement missing	200.00	Time to retire and remove Wiring may need to be secured as		
CLOSET: Phone and internet wiring should be secured Piano Insulation in basement missing where lift constuction took place	200.00			
CLOSET: Phone and internet wiring should be secured Piano Insulation in basement missing where lift constuction took place Pipes in basement from well need	200.00	Wiring may need to be secured as		
CLOSET: Phone and internet wiring should be secured Piano Insulation in basement missing where lift constuction took place Pipes in basement from well need ceiling hangars?	200.00	Wiring may need to be secured as well		
CLOSET: Phone and internet wiring should be secured Piano Insulation in basement missing where lift constuction took place Pipes in basement from well need ceiling hangars?	200.00	Wiring may need to be secured as well Alarm on holding tank indicates		
CLOSET: Phone and internet wiring should be secured   Piano   Insulation in basement missing where lift constuction took place   Pipes in basement from well need ceiling hangars?   Septic Tank Routine Pumping	200.00	Wiring may need to be secured as well Alarm on holding tank indicates		
CLOSET: Phone and internet wiring should be secured   Piano   Insulation in basement missing where lift constuction took place   Pipes in basement from well need ceiling hangars?   Septic Tank Routine Pumping   Routine Roof Inspection	200.00	Wiring may need to be secured as well Alarm on holding tank indicates		
CLOSET: Phone and internet wiring should be secured   Piano   Insulation in basement missing where lift constuction took place   Pipes in basement from well need ceiling hangars?   Septic Tank Routine Pumping   Routine Roof Inspection   Routine Lift Maintenance (recertify	200.00	Wiring may need to be secured as well Alarm on holding tank indicates		
CLOSET: Phone and internet wiring should be secured   Piano   Insulation in basement missing where lift constuction took place   Pipes in basement from well need ceiling hangars?   Septic Tank Routine Pumping   Routine Roof Inspection   Routine Lift Maintenance (recertify every 5 years)	200.00	Wiring may need to be secured as well Alarm on holding tank indicates		
CLOSET: Phone and internet wiring should be secured   Piano   Insulation in basement missing where lift constuction took place   Pipes in basement from well need ceiling hangars?   Septic Tank Routine Pumping   Routine Roof Inspection   Routine Lift Maintenance (recertify every 5 years)   Inspect / Repair siding, flashing	200.00	Wiring may need to be secured as well Alarm on holding tank indicates		
CLOSET: Phone and internet wiring should be secured   Piano   Insulation in basement missing where lift constuction took place   Pipes in basement from well need ceiling hangars?   Septic Tank Routine Pumping   Routine Roof Inspection   Routine Lift Maintenance (recertify every 5 years)   Inspect / Repair siding, flashing   Perimeter drains: Check, Flush,	200.00	Wiring may need to be secured as well Alarm on holding tank indicates		

			Regular inspections for evidence of		the museum collection continues to grow They are persistant		
			Chimney Roof		Flashing around chimney apparently needs inspection and perhaps attention Should be evaluated as the value of		
Priority	Status	Added	Item Ramp	Est Cost	Notes Showing signs of rot	Last Done	Nex
	ciety I	Museu					
			Kitchen needs makeover		wall cladding partially removed behind stove exposing cellulose insulation that is spilling out. Potential health and fire hazard		
			stairs NEED storage solution for chairs and tables				
			starting to peel Floor damage in foyer at bottom of				
			Update toilets / sinks for water conversation (less load on septic tank) Town Meeting Room ceiling is				
			floor staircase - stairs are SLIPPERY.		Manning suggested a rubber infused wood product that could be applied to the existing treads.)		
	 		Floor finish in Town Meeting Rm Rear fire escape (wooden) from 2nd		Annual clean and seal recommended. Every 2 years at a minimum? Resurfacing should be done soon (B		
			Regular inspections for evidence of critters in attic and basement (bats, mice & squirrels)		Bats love the belfry		
			ADA ramp needs regular sanding/sealing, nails need resetting, handrail is currently wobbly with at least one split section.		NB Almost 4 inch drop from end of ramp to paved walkway. UNACCEPTABLE for wheelchair access, and a tripping hazard.		
			Windows/Doors need to be inspected, adjusted and repaired as necessary to ensure operability				